

Material Safety Data Sheet

May be used to comply with
OSHA's Hazard Communication Standard.
29 CFR 1910.1200. Standard must be
consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration
(Non-Mandatory Form)
Form Approved
OMB No. 1218-0072



IDENTITY (As Used on Label and List) Note: Blank spaces are not permitted, if any item is not applicable or no information is available, the space must be marked to indicate that.

Section I ZINC ALLOYS

Manufacturer's Name ALLIED METAL CO.	Emergency Telephone Number 312/225-2800
Address (Number, Street, City, State, and ZIP Code) 2051 S. CANAL ST.	Telephone Number for Information 312/225-2800
CHICAGO, IL. 60616	Date Prepared 9/2/96
	Signature of Preparer (optional) <i>[Handwritten Signature]</i>

Section II — Hazardous Ingredients/Identity Information

Hazardous Component (Specific Chemical Identity; Common Name(s))	OSHA PEL	ACGIH TLV	Other Limits Recommended	% (optional)
ZINC	5MG/M ³	10MG/M ³		REMAINDER
COPPER	0.1MG/M ³	0.2MG/M ³		3.5% MAX
MAG	15MG/M ³	10MG/M ³		25% MAX
ALUM	15MG/M ³	10MG/M ³		28% MAX
IRON	10MG/M ³	5MG/M ³		20% MAX
TIN	2MG/M ³	2MG/M ³		0.1% MAX
LEAD	0.05MG/M ³	0.15MG/M ³		0.02% MAX
CADMIUM	0.05MG/M ³			0.015% MAX

Section III — Physical/Chemical Characteristics

Boiling Point APPROX. 1663	Specific Gravity (H ₂ O = 1) RANGE 5.0 - 7.18
Vapor Pressure (mm Hg) N/A	Melting Point APPROX. 780
Vapor Density (AIR = 1) N/A	Evaporation Rate (Butyl Acetate = 1) N/2
Solubility in Water NONE	
Appearance and Odor SOLID - BLuish-WHITE-NO ODOR	

Section IV — Fire and Explosion Hazard Data

Flash Point (Method Used) N/A	Flammable Limits N/A	LEL N/A	UEL N/A
---	--------------------------------	-------------------	-------------------

Extinguishing Media
USE DRY CHEMICAL OR CARBON DIOXIDE EXTINGUISHING MEDIA

Special Fire Fighting Procedures
ZINC DUST IS FLAMMABLE, WHEN SUSPENDED IN AIR AT CONCENTRATION EXCEEDING 430 G/M³

SELF-CONTAINED, BREATHING APPARATUS SHOULD BE USED WHEN FIGHTING A FIRE.

Unusual Fire and Explosion Hazards
ZINC DUST IN CONTACT WITH WATER OR ACIDS EVOLVES HYDROGEN. ZINC OXIDE FUME MAY REACT VIOLENTLY WITH CHLORINATED RUBBER. WET METALLIC ZINC WHEN CHARGED INTO MOLTEN METAL IS AN EXPLOSIVE HAZARD.

OSHA 174, Sept. 1985

20/10 206 222 1161 TO 1732377706 312 225 1161 TO 1732377706 00 7L CO FR ALLIED METAL CO JUL 07 '97 16:07

Section V — Reactivity Data

Stability	Unstable	Conditions to Avoid
	Stable	X UNDER NORMAL CONDITION OR TRANSPORTATION, STORAGE AND USE. ZINC DUST IN CONTACT WITH ACIDS EVOLVE HYDROGEN GAS. ZINC OXIDE MAY REACT VIOLENTLY WITH CHLORINATED RUBBER
Incompatibility (Materials to Avoid)		
Hazardous Decomposition or Byproducts		

Hazardous Polymerization	May Occur	Conditions to Avoid
	Will Not Occur	X

Section VI — Health Hazard Data

Route(s) of Entry:	Inhalation? YES	Skin? YES	Ingestion? NOT NORMALLY
Health Hazards (Acute and Chronic) INHALATION OF ZINC DUST OR ZINC OXIDE FUMES CAN CAUSE METAL FUME FEVER. SKIN AND EYE CONTACT TO DUST OR FUMES CONTAINING ZINC CAN CAUSE SKIN AND EYE IRRITATION.			
Carcinogenicity:	NTP?	IARC Monographs? NO	OSHA Regulated? NO

Signs and Symptoms of Exposure
METAL FUME FEVER SYMPTOMS INCLUDE HEADACHE, FEVER, CHILLS, MUSCLE WEAKNESS, VOMITING, NAUSEA, SYMPTOMS USUALLY START SEVERAL HOURS AFTER EXPOSURE.

Medical Conditions Generally Aggravated by Exposure
PRE-EXISTING UPPER RESPIRATORY AND LUNG DISEASE.

Emergency and First Aid Procedures
METAL FUME FEVER: REMOVE TO FRESH AIR. IF BREATHING BECOMES DIFFICULT, GIVE OXYGEN AND CALL A PHYSICIAN.

Section VII — Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled
IF METAL IS IN A SOLID FORM, COLLECT FOR REMELTING OR IF METAL IS IN A MOLTEN STATE, ALLOW TO COOL THEN COLLECT FOR REMELTING.

Waste Disposal Method
NOT A WASTE. COLLECT FOR RECYCLING - NOT FEDERALLY REGULATED.

Precautions to Be Taken in Handling and Storing
IF ZINC IS IN A MOLTEN STATE, AVOID CONTACT WITH WATER OR MOISTURE. IF IT IS IN A SOLID STATE, BE CAREFUL OF SHARP EDGES. STORE IN A DRY AREA. DO NOT ALLOW TO GET WET.

Other Precautions
USE SAFE FOUNDRY PRACTICES.

Section VIII — Control Measures

Respiratory Protection (Specify Type) REQUIRED WHEN CUTTING OR WELDING, USE PARTICLE MASK WITH ADEQUATE VENTILATION.			
Ventilation	Local Exhaust ONLY IF TLV'S OR PEL'S ARE EXCEEDED	Special	N/A
	Mechanical (General) N/A	Other	N/A
Protective Gloves	YES! TO PREVENT CUTS OR BURNS IF METAL IS HOT. AS NEEDED	Eye Protection	SAFETY GLASSES AND/OR FACE SHIELDS
Other Protective Clothing or Equipment	WHEN HANDLING MOLTEN ZINC, FIRE RETARDENT CLOTHING, FACE SHIELDS, HARD HAT, PROTECTIVE GLOVES & SPATS ARE RECOMMENDED.		
Work/Hygiene Practices	GOOD NORMAL HYGIENIC PRACTICES ARE TO BE FOLLOWED.		

THE INFORMATION GIVEN ON THIS FORM IS CORRECT TO THE BEST OF MY KNOWLEDGE AND GIVEN IN GOOD FAITH. THIS COMPANY ASSUMES NO LIABILITY FOR LOSS OR DAMAGES INCLUDED FROM THE PROPER OR IMPROPER USE OF THIS PRODUCT.